

Job Description

Job Title: Oxy-Fuel Burning Operator

Department: Welding

Summary: Responsible for producing on time quality burning work by performing the duties and responsibilities outlined below:

Duties and Responsibilities include, but not limited, to the following. Other duties may be assigned.

1. Prepare and set up appropriate tools and equipment needed to perform steel plate burning tasks.
2. Ensure that all gas pressure settings are within appropriate burning parameters.
3. Maintain good housekeeping in your work area of responsibility
4. Take good care of equipment from your burning machines to your burning tips and tracks.
5. Maintain consistency of profile when burning bevels.
6. Communicate with your lead-man in all aspect (safety, productivity and quality) of work
7. Check completed work to ensure conformity to drawings and procedures.
8. Always achieve high production with good quality output.
9. Work and think safety at all times.

Skills:

Oral Communication Skills

Reading Skills

Blue Print Reading

Reading Skills

Time Management

Basic Layout Skills

Physical Dexterity

Experience:

At least two to three years experience in burning compound bevel profiles